## MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible: yes \_\_\_\_\_ no \_\_\_\_

roperty Name: Dr. Peter L. Calomeris, General Dentistry	Inventory Number: M: 29-63
Address: 11421 Falls Road	Historic district: yes X no
City: Potomac Zip Code: 20854	County: Montgomery
USGS Quadrangle(s): Rockville	
Property Owner: Peter L. and L.V. Calomeris	Tax Account ID Number: 00852290
Tax Map Parcel Number(s): P037 Tax Map Num	nber: FQ51
Project: Falls Road Hiker/Biker Trail Ager	ncy: Montgomery Co Dept of Public Works & Tr
Agency Prepared By: John Milner Associates, Inc.	
Preparer's Name: Sarah Traum	Date Prepared: 3/14/2005
Documentation is presented in: Montgomery County Historical Society	
Preparer's Eligibility Recommendation: Eligibility recommende	d X Eligibility not recommended
Criteria: A B C D Considerations: A	BCDEFG
Complete if the property is a contributing or non-contributing resou	
Name of the District/Property:	× ***
Inventory Number: Eligible:	yes Listed: yes
site visit by MHT Staf yesX _ no Name:	Date:
Description of Property and Justification: (Please attach map and photo)	
This property contains a Colonial Revival dwelling and a two-car garage on larg form, with a shallow, cross gable at the north end of the historic core. The historic deep. Most of the core's exterior is sheathed with painted brick, although the set siding. The slate roof has a closed rake. The windows are one-over-one doubleby shutters. The front (west) entrance is a wood paneled door with sidelights and rises through the rear (east) roof slope. A hipped-roof porch stretches across the and wooden Tuscan columns for support.	ric core measures three bays wide and three bays cond floor of the projecting ell is clad with vinyl hung sash with brick rowlock sills and are flanked d an elliptical fanlight. A brick interior chimney
Two one-story additions are located on the north elevation of the historic core. It of these two additions is three bays wide and one bay deep, with a brick exterior north gable end. The other addition is three bays deep and is a frame structure of	. This addition has a large Palladian window in its
A one-story garage with parged exterior is located northeast of the house. This to gable roof and six-over-six double-hung sash flanked by shutters. An in-ground	
MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended Eligibility not recommended >	
Criteria:ABCD Considerations:A	BCDEFG
MHT Comments:	
7.71	-1-1
Reviewer, Office of Preservation Services	5/5/05 Date
Blanti-	126/05
Reviewer, National Register Program	Date

## NR-ELIGIBILITY REVIEW FORM

M: 29-63

## Dr. Peter L. Calomeris, General Dentistry

Page 2

house. An asphalt drive leads to the property from Falls Road. This drive expands into a paved parking area northwest of the house. Foundation plantings ring the house and its large lot has scattered mature trees. A board fence, with brick posts at the entrance to the driveway, demarcates the edge of the property along Falls Road.

Through the mid-twentieth century, the area around the south portion of Falls Road in Montgomery County, where this property is located, was focused on agriculture, with many small farms along the road. At the south end of Falls Road is the crossroads community of Potomac (formerly Offutt's Crossroads). This community grew up in the early nineteenth century to serve the needs of local residents. Beginning in the mid-twentieth century, many of the small farms along Falls Road were purchased for subdivision for new housing developments (Sween and Offutt 1999:171).

According to assessment records, this house was built in 1940. No building appears at this location on a 1923 Rockville, MD.-VA. quadrangle, but there is a building here on the 1944 version of this map (USGS 1923, 1944). The additions to the building were built in 1984 (Montgomery County Permitting Services, Permit # 83B090065).

This property is not recommended eligible for listing in the Maryland Inventory of Historic Places and the National Register of Historic Places. The additions to this building diminish the integrity of design for the historic core, as these additions are similar in scale to the original building. These additions and alterations to the building have impacted its integrity of materials through the introduction of modern materials, such as vinyl siding, and the vinyl windows. This house does retain its original setting, that of a large suburban lot.

References cited:

Sween, Jane C., and William Offutt

1999 Montgomery County: Centuries of Change: An Illustrated History. Sun Valley, CA: American History Press.


United States Geological Survey (USGS)


1923 Rockville, MD.-VA., Quadrangle, 15-minute series. United States Geological Survey. Washington, D.C.

1944 Rockville, MD.-VA., Quadrangle, 15-minute series. United States Geological Survey. Washington, D.C.

MARYLA	AND HISTO	RICAL T	RUST RE	VIEW							
Eligibility recommended		ed	Eligibility not recommended								
Criteria:	A _ nments:	_в _	_Cl	Considerations:	A	_В	c	D	E	F	G
	Reviewe	r, Office	of Preserv	ation Services			Date				
	Reviewer, National Register Program			Date							

M:29-63





Rockville, MD-VA. 7.5-minute quadrangle. Reston, VA:1984. M:29 - 63

POTOMAC VICINITY MONTE-OMERY GO.



M: 29-63
DR. PETER L. CALOMERIS, GENERAL DENTISTRY
11421 FALLS RD
MONTGOMERY CO., MD
S. TRAVM 212005 NEGATHE E MD SHOO W & S ELEVATIONS #1/2 or House MILANA MILYA

BALANA

Med-01223( > )029 516 0611 H N N 2 12 2(040) (0

Yak



M. 29-63 L. CALOMERIS, GENERAL DENTISTRY
II4 21 FALLS RD
MONTGOMERY CO, MD
S. TRAUM
2/2005
NEGATIVE AT MD SHPO
NEGATIVE AT MD

Mad. 012234 2028 516 0611 H H N 1 2# 2(040)@